

Title: Uninterruptible power supply stinks

Generated on: 2026-06-08 04:59:27

Copyright (C) 2026 GAE CONTAINERS. All rights reserved.

---

It's normal for new Transformers to release some harmless odors from the varnish impregnation used in the coils for a week or two after energization. Older Transformers can also release ...

It might have just been some dust if the PC hasn't been on for a while, but since you said it was like a plastic smell it's not worth the risk to your other components or the possible fire risk in a ...

I tried connecting my old psu but it only has a 6 pin connector for the GPU, what should I do? Get another psu, that's all you can do really. Don't take shortcuts with power ...

Thankfully, some of our clients had the mis-fortune to witness the smell emitted by this UPS so blocking any further procurement of Eaton devices for use in an office ...

Running a PSU that has a burning smell to it, even if you don't notice any immediate performance issues, is not good practice. If it isn't smoking yet, you probably have ...

A burnt smell can be alarming, and understanding the root cause can save you from extensive repairs or replacements down the line. In this article, we will delve into the potential reasons ...

Website: <https://www.gaeconsultants.co.za>

